



# Which kind of inspection requirements are there ?



- The integrated technologies are to consist of several technologies related to the solution for client(s)' requirements.
- The integrated solutions are to be designed considering not only an inspection device, but also production efficiency through a whole production line.



- ✓ To minimize defectives (Non-conforming articles) in the production process
- ✓ To improve the production process including defective analysis